

Two Phase Stepper Motor Torque Curve

Stepper Motor Torque Curve

















Driving Mode: Constant current drive

Driving Voltage: 24V DC

Excitation Mode: 2 phase

Remarks: Peak current is equal to $\sqrt{2}$ times effective value.

















— Peak Value
— Effective Value



Stepper Motor Torque Curve
Driving Mode: Constant current drive
Driving Voltage: 24V DC
Excitation Mode: 2 phase
Remarks: Peak current is equal to $\sqrt{2}$ times effective value.



















— Peak Value
— Effective Value



Two Phase Stepper Motor Torque Curve

Stepper Motor Torque Curve
Driving Mode: Constant current drive
Driving Voltage: 24V DC
Excitation Mode: 2 phase
Remarks: Peak current is equal to $\sqrt{2}$ times effective Value.

















— Peak Value
— Effective Value



Two Phase Stepper Motor Torque Curve

Stepper Motor Torque Curve
Driving Mode: Constant current drive
Driving Voltage: 24V DC
Excitation Mode: 2 phase
Remarks: Peak current is equal to $\sqrt{2}$ times effective Value.

















— Peak Value
— Effective Value



Two Phase Stepper Motor Torque Curve

Stepper Motor Torque Curve
Driving Mode: Constant current drive
Driving Voltage: 24V DC
Excitation Mode: 2 phase
Remarks: Peak current is equal to $\sqrt{2}$ times effective Value.

— Peak Value
— Effective Value



Two Phase Stepper Motor Torque Curve

Stepper Motor Torque Curve
Driving Mode: Constant current drive
Driving Voltage: 24V DC
Excitation Mode: 2 phase
Remarks: Peak current is equal to $\sqrt{2}$ times effective value.



— Peak Value
— Effective Value

